FloPlast

building the future

Step by Step Installation Guide - STRAP ON BOSS (SP319)



✓ Cut a 54mm hole into the soil pipe.



Solvent weld around the hole and the flange of the Strap on Boss.



✓ The Strap on Boss has a built in fall of 2½ degrees.

✓ The word 'top' is embossed on the fitting to show the correct way up.



Push fittings together to secure bond.



Squeeze the clips at the back together to secure the Strap on Boss to the soil pipe.



✓ For Push-Fit connections 32/40/50mm to pipe, use rubber boss adaptors SP10/11/12.



- Solvent cement fittings together to secure bond.
- ✓ For Solvent Weld connections, use solvent weld adaptors SP20/21/22.

For further information, please visit out website: www.floplast.co.uk



FOR SOLVENT WELD

APPLICATIONS