



FastFlo Shower Trap

Tip:
Run the trap under hot water for 30 seconds before installation. It will be much easier to turn the outlet.



FloPlast
building the future

FloPlast Ltd
Castle Road
Eurolink Business Park
Sittingbourne
Kent
ME10 3FP

Tel: +44 (0) 1795 431731
Website: www.floplast.co.uk